

CHALLENGES:

Renewing the 30-year-old Pines Golf Course irrigation system to meet current and future levels of service was long overdue. The project had a few key challenges the team needed to overcome:

- **Ground Movement:** The materials and processes had to be flexible enough to withstand ground movements caused by soil composition and water table changes.
- **Trenchless Installation Methods:** The team wanted to reduce the amount of open trenches dug in the installation process to minimise damage to the fairways and shorten the return to course playability time.
- **Welded Water Mains:** The team wanted a secure welded fitting between the mains and the irrigation system reducing the pipe size to 63mm, that would stand the test of time and reduce maintenance requirements.
- **Time Pressure:** The Pines Golf Course was under pressure from its members to have the course back up and running in as short amount of time as possible.

SOLUTION:



TRUNK MAINS

PE pipes ranging from 125mm through to 315mm OD were joined by butt welding and electrofusion welding and installed by typical open trench outside the fairway.



CONNECTING TO LATERALS

Plasson electrofusion branch saddles were used to achieve smaller connections (63mm) from the large mains. The welded electrofusion branch saddles become homogenous with the pipe, making the joint stronger than the main pipe on its own.



ISOLATION VALVES

Plasson 63mm PE100 Ball Valves with PE spigot ends provided a fully welded solution up to and including the lateral isolation valves. The unique, fully injection-moulded one-piece design eliminates internal cavities and trapped dirt, while riser activation allows for a smaller, round valve pit.



LATERALS

A vibratory plough was used to install the 63mm PE through the fairways and around the greens. Metric compression fittings such as tees, elbows and tapping saddles were used to connect to sprinkler risers.



SPRINKLER CONNECTIONS

Depending on the location of the sprinkler in relation to the 63mm lateral, either mechanical tapping saddle or 63x 1.1/4" metric female elbow fittings were used to connect the sprinkler articulated riser.

SANCTUARY COVE GOLF.

PLASSON
AUSTRALIA

THE PINES GOLF COURSE IRRIGATION UPGRADE

Pines Golf Course | Sanctuary Cove QLD



CASE STUDY



“Partnering with Plasson who have a reputation for quality products not only gave us confidence but also for the installation team, design team and asset owner.”

STEVE MONCRIEFF

BUSINESS DEVELOPMENT MANAGER | NUTRIEN WATER NERANG

The original irrigation system at The Pines Golf Course, dating back to 1988, had reached the end of its design life, making a full renewal essential. In November 2019, work began to upgrade the system to meet modern performance standards and future service requirements and was completed in May of 2020.

Nutrien Water Nerang, in partnership with experienced golf industry subcontractor Prolinks, was commissioned to deliver the project at Sanctuary Cove Golf Club on the Gold Coast.

After careful assessment, the team recommended a polyethylene (PE) pipe system paired with Plasson fittings, selected for their durability, efficiency, and suitability for large-scale golf course installations.

PROJECT PARTNERS:

Irrigation Contractor: **Nutrien Water Nerang**

Irrigation Installer: **Prolinks**

Irrigation Design: **Hydro Pumping & Controls**

Timeline: **November 2019 – May 2020**



RESULTS AND IMPACT:

The finished product achieved by Nutrien Water Nerang and Prolinks with Plasson's PE system met all of the project requirements, and with PE pipes and electrofusion fittings provided a system with a service lifetime of over 100 years. Some of the benefits of the Plasson system are:



FATIGUE FAILURE RESISTANCE

Polyethylene (PE) materials used in the system provide a high fatigue failure resistance compared to the existing PVC piping and ductile-lined fittings.



PN16 PRESSURE RATING

Plasson fittings are third party certified to PN16 pressure rating. This easily exceeded the system design giving peace of mind.



GROUND MOVEMENT TOLERANCE

The material characteristics of PE systems can accommodate the ground movements that can damage a PVC system.



TRENCHLESS INSTALL

Vibratory plough was used to install the 63mm PE laterals. This reduced the number of joins and allowed a faster recovery time allowing play to resume in most cases within 2 weeks of installation starting.



LONG TERM SOLUTION

With a system operating pressure of around 750 kpa, Plasson's electrofusion and spigot fittings have an expected service lifetime of over 100 years.



RECYCLED MATERIALS

Excess PE pipe and offcuts were ground down and recycled by Nutrien Water Nerang as pit bases, reducing waste and providing a cleaner finished installation.

